



The diagram shows a technical drawing of a mechanical part with two circular features. A dashed line indicates the "limite de la zone d'usinage" (limit of machining zone). Dimensions include 60x1, 60x1.8, 100, and 100. A note specifies "pas de chanfreux sur cette face" (no chamfer on this face). The origin of mass reference is indicated by a circled cross symbol.

[illegible]